

Office of Safe and Orderly Schools
Facility Safety Assessment
Mark Hobson, School Facilities Supervisor
Dennis Meador, School Facilities Supervisor
Division of School Buildings
January 26-27, 2011

Items in red were complete on 7-26-2011.

Please accept the following findings for consideration at each school site. If we may assist you by providing additional information regarding this report, you may contact us at (601) 359-1028.

Drew Municipal School District
Mr. Charles Barron, Acting Superintendent

Drew Hunter High School
Mr. Edgar Holman, Principal
Attended by: Mr. Moody, Maintenance

Findings:

Classrooms

- There were extension cords being used as a permanent power source in rooms 7, 19 and the Career discovery room.
- There was an unprotected electrical outlet on the East wall of room 7.
- There were no evacuation maps in rooms 5 and 22.
- There were missing ceiling tiles in room 25.
- There was an unprotected hot water heater in room 27.
- Hot water heater in room 27 had an out of date certificate.

Restrooms

- There were no urinals in the boys' restroom in the main hall.

Hallways

- There was exposed plumbing where a drinking fountain used to be outside the library.

Gymnasium

- Northwest exit sign was missing its lens.
- There was exposed plumbing where a drinking fountain used to be in the foyer.
- There were exit signs being powered by extension cords.
- There were missing ceiling tiles in the foyer.
- There were exposed wires by the East exit door.
- There were unprotected lights in the boys' and girls' restrooms in the foyer.
- There were unprotected lights in the shower in the boys' dressing room.

- There was an inoperable urinal in the boys' dressing room.
- There was a discharged fire extinguisher on the playing surface.
- There were unprotected lights in all four corners of the gymnasium by the dressing rooms.

In School Suspension Building

- There were some unprotected fluorescent lights.
- There were unprotected lights in the restroom.
- There was no evacuation map in the classroom.

Boiler Room

- There was a discharged fire extinguisher.
- There were missing blanks in the electrical panel.

Kitchen/Dining Area

- There was an extension cord on the ice cream box by the serving line.
- There were unprotected lights in the dish washing area.
- There were missing blanks in the electrical panel in the cooking area.
- Food was stored on the cooler floor.
- There were unprotected lights in the dry goods area.
- There were exposed wires hang from the ceiling in the dry goods area.
- Vent Hood had not been professionally cleaned in over two years.
- There was a damaged electrical outlet on the West wall of the dining area.
- East exit door was damaged.

A. W. James Elementary School
Mrs. Jacqueline Lockett, Principal
Attended by: Mr. Moody, Maintenance

Findings:

Gymnasium

- There was an out of date fire extinguisher.

Classrooms

- There were extension cords being used as a permanent power source in the library.
- There were curtains on the second means of egress windows in several rooms.
- There were extension cords being used as a permanent power source in rooms 1, 6 and 8.

Exterior

- There were exposed fan wires on the A/C units outside the Gymnasium.
- Electrical A/C panels were unsecured.

Kitchen/Dining Area

- There was an extension cord on the serving line.
- There was no emergency lighting over the main doors leading into the hallway.
- Electrical breaker panel cover was missing in the kitchen.

Old Drew High School

Attended by: Mr. Moody, Maintenance

Findings:

Parent Center

- There was an inoperable exit sign.
- There was an extension cord being used as a permanent power source for the wall clock.

Gymnasium

- There were some unprotected lights outside the gymnasium.
- There were unprotected lights in the dressing rooms.
- There were damaged exit signs.
- There was damaged emergency lighting.
- There were deadbolt locks main exit doors.
- There were slide locks on main exit doors.
- There was a discharged fire extinguisher on the playing surface.
- There were exposed wires on ceiling fans in home boys' dressing room.
- Seating capacity was not posted.

Gymnasium Foyer

- There were exposed wires on the south heater.
- There was damaged panic hardware on exit doors.
- There were missing door closers on exit doors.
- There was no fire extinguisher.
- There were no exit signs.
- There was no emergency lighting.
- There were unprotected lights in the restrooms.